
WEIGHING INDICATOR user manual

Model: TI-02


Please read this manual carefully before operation

- ----Important safety info
- ----Operating condition and other attentions
- ----Guarantee info

Important Safety And Operation Info




Please read the manual in details before operation.



A

Please use the right plug and right voltage Be much attention of 110V or 220V!!!



Don't clean the indicator with the flush water.



Keep it away from the corruptive gas or liquid.



Don't touch the keypad with the items with sharp end.



Don't open the indicator by yourself and please call the service people or our distributor when you get the problem with it.



Please recharge the scale on time to assure the health of the battery, and replace the battery if it runs out of life. The replaced battery must be handled correctly.

INDEX

Specifications	4
Power	
Before using	
System power consumption	4
Display description	4
Basic function operation	5
Connection of load cell and RS232	5
Basic parameter setting	
UF-1 A/D count	6
UF-2 High / Low limits setting	6
UF-3 Auto-power off	7
UF-4 Backlight setting	7
UF-5 Hold function (*)	7
UF-6 RS-232 output	8
UF-7 Speed setting (*)	10
UF-8 Zero tracking (*)	10
UF-9 G Value setting	11
UF-10 Filt setting	11
UF-12 Beep setting	11
Weight Calibrations (*)	12
ECF-1 Zero and Span Calibration	12
ECF-2 Zero Calibration	12
ECF-3 Span Calibration	12
Guarantee	13

SPECIFICATIONS

Accuracy: Class III Nonlinear: ≤0.01%F.S

Excitation voltage: DC 5V,up to 4 load cells 350 Ω Large display connector: Sampling serial output way

Sample rate: 20 times per second (can select)

POWER

Input: 120~240V Output: 9V/500mA

Rechargeable battery: 6V/1.3AH

BEFORE USING

- 1) Place this product on a firm and smooth place, don't place it in vibration or shaking, use bench for use on four only adjust foot, adjust the balance using the bubble level.
- 2) Use independent source, avoid other electrical disturbance.
- 3) Don't put any object on the platter when turn on the balance.
- 4) Please, turn on 2-3 minutes before using.
- 5) Avoid temperature change too large and air flow strenuous sites.
- 6) Don't overload the balance, don't exceed the maximal capacity.

SYSTEM POWER CONSUMPTION

Main system power consumption: about 12mA

Main system power consumption (with backlight): about 36mA

Main system power consumption (with backlight and RS-232): about 48mA

Battery life: none backlight, about 320 hours.


DISPLAY DESCRIPTION

TI-02 Model:

BASIC FUNCTION OPERATION



Press and hold this key for 2 seconds to turn off the balance.





Function 2. To reset the weight to "0", but the display value has to be lesser than \pm 2% of maximum capacity.


Function 3. To subtract the container's weight.

Function 4. To move one space to the right or upward in setup mode.



Function 1. To select the desired weight unit.

Function 2. To exit from setup mode.



All other keys will be disabled when gross weight is activated.

Function 2. To increase values upward in setup mode.





Function 2. Manually transmitting data through RS232 to computer or printer.

Function 3. To accumulate weights, the max of the weight times is 9999




Function 1. To recall accumulations

Function 2. Long press the key will clear accumulated weight

Function 3. To move one space to the left or downward in setup mode.


CONNECTION OF LOAD CELL AND RS232

1) Connection of the load cell to indicator



INDICAT	OR	LOAD CELL
1		+Excitation
2		+Sense
3		-Excitation
4		-Sense
5		+Signal
6		(GND) shield
7		-Signal

2) Connection of RS232 to PC or Printer



INDICATO	OR PO	C/PRINTER
1		RXD
2		TXD
3		GND
4		NC

BASIC PARAMETER SETTING

To access to functions setting, press the $\frac{1}{2ero/Tare}$ and $\frac{1}{4}$ key at the same time in weighing mode. Press the $\frac{1}{2ero/Tare}$ key to select the parameter ($\frac{1}{UF-1}$)

"*" This flag indicates that the function is locked when "Approval Version".

UF-1 A/D count

- 1. Press the key to view the A/D count.
- 2. Press the key to view the the battery voltage or press the back to menu UF-1
- 3. To move to next parameter press the Zero/Tare key.
- 4. To exit and return to normal weighing press the LINIT key

UF-2 High / Low limits setting

- 1. Press the key to enter.
- 2. The display will show [00.000] (set low limit).
- 3. Use the keys and zero/Tare and press the number.
- 4. Press the key to confirm.
- 5. The display will show 00.000H (set high limit).
- 6. Use the keys and and to move cursor and press the Net/Gross to select number.
- 7. Press the key to confirm.
- 8. The display will show \bigcirc .000 ,look at the remarks below.
- 9. Use the keys and Zero/Tare and Zero/Tare to move cursor and press the Net/Gross to select

number.

10. Press the key to confirm.

Remarks: 0 0 0

A B C

A --- Buzzer on: 0= Stable not required 1= Stable required

B -- LCD indicator and RELAY on: 0= Stable not required 1= Stable required

C: Buzzer beeps when: 0= Buzzer off 1= OK 2= LO and HI

- Low limit set as 0 will clear all check weigh values.
- This function is locked when UF-5 is set as "Hold 1"

UF-3 Auto-power off

Modes: Aoff00 :Auto-turn off disable.

Aoffol : The balance will automatically turn off after 1 minute of non use.

This time can be set up to 99 minutes.

- 1. Press the key to access to auto-power configuration.
- 2. Use the keys and zero/Tare and press the number.
- 3. Press the key to confirm.

UF-4 Backlight setting

Modes: lit a : Automatic

lit on : Backlight on

litoff : Backlight off

- 1. Press the key to access to backlight configuration.
- 2. Use the Net/Gross key to select the desired mode.
- 3. Press the key to confirm.

UF-5 HOLD function (*)

Modes: Hold 0 : Disable

Hold 1 : Animal (motion) Hold function

Hold 3: Stable hold (when held can press any key to cancel) Hold 4: Stable hold (when held can auto cancel at zero) key to access to hold function configuration. 1. Press the 2. Use the Net/Gross key to select the desired mode. 3. Press the key to confirm. Remarks: Hold 1 key will show PCT002 1. Press the to move cursor and press the Net/Gross to select 2. Use the keys. and number, this can set the range from 001 ~ 100 units of the animal hold. key will show Time 8 3. Press the 4. Use the Net/Gross key to select 1,2,4,8,16,32 or 64 times within the hold range. 5. Press the key to confirm. **RS-232 Output** UF-6 key to enter. 1. Press the 2. The display will show 232 1 . 3. Press the Net/Gross key to select the modes. key to confirm, and will show b 9600 . 4. Press the 5. Use the Net/Gross key to select the baud rate. key to confirm. 6. Press the Modes: 232 0: RS-232 disable 232 1 : Stable output – Format 1 2 : Stream output – Format 1 232 3 : Manual output – Format 1 232 232 4 : Stable output – Format 2 5 : Stream output – Format 2 232 6: Manual output – Format 2 232

Hold 2: Peak value hold (when held can press any key to cancel)

232 7 : Manual accumulate output – Format 3

232 8 : Auto accumulate output – Format 3

232 9 : Manual accumulate output – Format 4

232 10 : Auto accumulate output – Format 4
232 11 ~ 232 13 : LP50 printer is used

Baud rate: B 1200 : Baud rate 1200

B 2400 : Baud rate 2400
B 4800 : Baud rate 4800
B 9600 : Baud rate 9600
B19200 : Baud rate 19200

B38400 : Baud rate 38400

Remarks:


Format 1 output examples: ST, GS, + 1.0001b

Format 2 output examples : + 1.0001b

Format 3 output examples:

S/N	WT/1b	
0001 0002	2. 205 2. 205	
0002	4. 410	

Format 4 output examples :



 Format 3 and format 4 if you want to print the total weight, press the twice, and the accumulative weight will be removed.



Communication Protocol:


UART signal of EIA-RS232 C


Format:

Baud rate: 9600
 Data bits: 8 bits
 Parity bits: None
 Stop bits: 1 bit

Format 1 (232 1-3):

OL – Overload	
ST – Stable	NT – Net weight
US – Unstable	GS – Gross weight





UF-7 Speed setting (*)

Modes: Speed : Standard speed

spEED2 : High speed spEED3 : Low speed

- 1. Press the key to enter.
- 2. Press the Net/Gross key to select the desired mode.
- 3. Press the key to confirm.

UF-8 Zero tracking(*)

Modes: Zp 0 : OFF

Image: Ima

- 1. Press the key to enter.
- 2. Press the Net/Gross key to select the desired mode.

3. Press the key to confirm.

UF-9 G Value setting

- 1. Press the key to display the G value of manufacture place.
- 2. If set the G value of local press the key and then press the Zero/Tare or



3. Press the key to confirm.

UF-10 Filt setting

- 1. Press the key to enter.
- 2. Press the Net/Gross key to select the desired mode.
- 3. Press the key to confirm.

UF-12 Beep setting

 $\begin{array}{ccc} \textbf{Modes:} \ \underline{\texttt{yS}} & \texttt{oN} \ \ : \textbf{ON} \\ \\ \underline{\texttt{yS}} & \texttt{oFF} \ \ : \textbf{OFF} \end{array}$

- 1. Press the key to enter.
- 2. Press the Net/Gross key to select the desired mode.
- 3. Press the key to confirm.

Weight Calibrations (*)

1. In weight mode, press the MR/MC and keys, the display will show ECF-1.

2. Press the or Zero/Tare or MR/MC key to select ECF-1, ECF-2 or ECF-3

ECF-1 Zero and Span Calibration

- 1. Press the key to enter, display will show CALZ
- 2. Press the key to calibrate zero point.
- 3. The display will show the calibration weight 00.6.000.
- 4. Use the keys Zero/Tare and MR/MC to select the digit, press key to input the weight value.
- 5. Put the calibration weight on the platter and press the key to calibrate.

 The scale will return back to weighing mode automatically.

ECF-2 Zero Calibration

- 1. Press the key to enter, display will show CALZ
- 2. Press the key to calibrate zero point.
- 3. The scale will return back to weighing mode automatically.

ECF-3 Span Calibration

- 1. Press the key to enter, display will show the calibration weight 00.6.000.
- 2. Use the keys and and weight value.
- 3. Put the calibration weight on the platter and press the key to calibrate.

 The scale will return back to weighing mode automatically.

GUARANTEE

This scale is guaranteed for one year from the delivery date. The guarantee covers any fabrication defect of the material.

During this period Gravity covers the labour cost and the spare parts necessary for the reparation of the scale.

This guarantee does not cover the failures caused by an inappropriate use or overcharge.

The guarantee does not cover the freight cost (transport) necessary to repair the scale.

Officially	Distributed	Ву